TOYOTA

MATERIAL HANDLING

# COSHH Risk Assessment:

## Part Number: 11667-CED

| | | | |
|---|---|---|---|
| Name of Substance involved in the process *(a copy of the current safety data sheet is available)* | CAFLON BS6580 | Pseudonym | Antifreeze Blue |
| Describe the activity or work process & exposure *(Inc. how long/how often this is carried out)* | FLT Maintenance Use: Infrequent, less than daily, short periods | Location of process being carried out | Customers Site Toyota Workshops |

| Identify the persons at risk | Team members | Sub-contractors | Customer Team member | Public |
|---|---|---|---|---|
| | √ | | | |

**Labelling Elements**


Explosive ☐


√ Health Hazard


√ Serious Health Hazard


Oxidising ☐


Corrosive ☐


Acute ☐


Flammable ☐


Environmental ☐


Gas ☐

Signal Word - WARNING

**Hazard Type**

| Gas | Vapour | Mist | Fume | Dust | Liquid | Solid | Other |
|---|---|---|---|---|---|---|---|
| ☐ | √ | √ | ☐ | ☐ | √ | ☐ | ☐ |

Additional Information:

**Route of Exposure & Possible Symptoms**

| Inhalation | Skin | Eyes | Ingestion | Other |
|---|---|---|---|---|
| √ | √ | √ | √ | ☐ |

Additional Information: Vapours in high concentrations are anaesthetic. Symptoms following overexposure may include the following: Headache. Fatigue. Dizziness. Central nervous system depression. Ingestion of large amounts may cause unconsciousness. Harmful if swallowed. May cause damage to organs (Kidneys) through prolonged or repeated exposure if swallowed.

**Control Measures**

Harmful if swallowed. May cause damage to organs through prolonged or repeated exposure.
Do not breathe vapour/ spray and mists. Wash contaminated skin thoroughly after handling. Do not eat, drink or smoke when using this product.
Avoid spilling. Avoid contact with skin and eyes.
Ensure there is adequate ventilation when using. If ventilation is inadequate, suitable respiratory protection must be worn. Wear a respirator fitted with the following cartridge: Combination filter, type A2/P3.

**This product poses no significant risk if used as intended in the amount anticipated, and manufactures instructions are followed.**

| Is health surveilance or monitoring required? | Yes | No |
|---|---|---|
| | ☐ | √ |

Provide details:



Authorisation: QSE Manager
Approval: QSE Team

## COSHH Risk Assessment:

**Part Number: 11667-CED**

| Personal Protective Equipment Required | | | | | | | |
|---|---|---|---|---|---|---|---|
|  |  |  |  |  |  |  |  |
| Dust Mask | Visor | Respirator | Goggles | Gloves | Overalls | Footwear | Other |
| | | | EN166. | EN374. | | | |

Additional Information:

| First Aid Measures | |
|---|---|
| **Inhalation:** | Move affected person to fresh air at once. Get medical attention if any discomfort continues. |
| **Skin Contact:** | Remove contaminated clothing immediately and wash skin with soap and water. Get medical attention if any discomfort continues. |
| **Eye Contact:** | Rinse immediately with plenty of water. Remove any contact lenses and open eyelids wide apart. Continue to rinse for at least 15 minutes. Get medical attention if any discomfort continues. |
| **Ingestion:** | Move affected person to fresh air and keep warm and at rest in a position comfortable for breathing. Rinse mouth thoroughly with water. Give plenty of water to drink. Get medical attention immediately. |

| Storage |
|---|
| Store in tightly-closed, original container in a dry, cool and well-ventilated place. Avoid excessive heat for prolonged periods of time. Materials to avoid: Strong oxidising agents. Strong acids. Strong alkalis. |
| **Spillage** |
| See SWP-19. Spillages or uncontrolled discharges into watercourses must be reported immediately to the Environmental Agency or other appropriate regulatory body. Absorb spillage with inert, damp, non-combustible material. Flush contaminated area with plenty of water. Collect and place in suitable waste disposal containers and seal securely. Wear PPE as detailed. |
| **Disposal of Substance & Contaminated Containers** |

| | | | | |
|---|---|---|---|---|
| | | √ | | |
| Hazardous Waste | General Waste | Depot | Return to Supplier | Other |

Additional Information: Waste is classified as hazardous waste. Do not puncture or incinerate, even when empty. Dispose of waste to licensed waste disposal site in accordance with the requirements of the local Waste Disposal Authority.

| Is exposure adequately controlled | Yes √ | No | |
|---|---|---|---|
| **Risk Rating Following Control Measures** | | | |
| High | | Medium | | Low √ | |
| Assessed by: | Elaine Greaves | Date: | January 2024 | Review Date: | July 2026 |