TOYOTA

MATERIAL HANDLING

COSHH Risk Assessment:

Part Number: 28168

Name of Substance involved in the process *(a copy of the current safety data sheet is available)*	Black Spray Paint	Pseudonym	Spray Paint
Describe the activity or work process & exposure *(Inc. how long/how often this is carried out)*	FLT Maintenance & Refurbishment, Infrequent use, less than weekly for seconds or minute or so at a time	Location of process being carried out	Customer Site & TMHUK Workshop

Identify the persons at risk	Team members	Sub-contractors	Customer Team member	Public
	✓			

Labelling Elements


Explosive ☐


Health Hazard ✓


Serious Health Hazard ☐


Oxidising ☐


Corrosive ☐


Acute ☐


Flammable ✓


Environmental ☐


Gas ☐

Signal Word: DANGER

Hazard Type

Gas	Vapour	Mist	Fume	Dust	Liquid	Solid	Other
☐	✓	☐	☐	☐	✓	☐	☐

Additional Information: Aerosol

Route of Exposure & Possible Symptoms

Inhalation	Skin	Eyes	Ingestion	Other
✓	✓	✓	✓	☐

Additional Information: Eye Irritant. May cause nausea, headache, dizziness and intoxication.

Control Measures

Extremely flammable aerosol. Pressurized container: Do not pierce or burn, even after use.
Keep out of reach of children.
Use in a well ventilated area.
Wear protective gloves/protective clothing/eye protection/face protection (See SWP-32). Keep away from heat, sparks and open flame, do not spray on an open flame or other ignition source.. Avoid inhalation of vapours and aerosol spray. Avoid contact with skin and eyes.
DO NOT SMOKE IN WORK AREA! Wash hands at the end of each work shift and before eating, smoking and using the toilet. Promptly remove any clothing that becomes contaminated. When using do not eat, drink or smoke.
This product poses no significant risk if used as intended in the amount anticipated, and manufactures instructions are followed.

Is health surveilance or monitoring required?	Yes	No
	☐	✓

Provide details:

Authorisation: QSE Manager
Approval: QSE Team

COSHH Risk Assessment:

Part Number: 28168

Personal Protective Equipment Required							
 ☐	 ☐	 ☐	 ✓	 ✓	 ✓	 ✓	 √
Dust Mask	Visor	Respirator	Goggles	Gloves	Overalls	Footwear	Other
Additional Information: All handling should only take place in well-ventilated areas. In case of inadequate ventilation or risk of inhalation of vapours, use suitable respiratory equipment with combination filter (type A2/P3).							

First Aid Measures	
Inhalation:	Move affected person to fresh air and keep ward and at rest in a position comfortable for breathing.
Skin Contact:	Wash skin thoroughly with soap and water
Eye Contact:	Rinse with water. Get medical attention if any discomfort continues.
Ingestion:	Drink a few glasses of water or milk. Do not induce vomiting

Storage
Keep out of reach of children. Store locked up in a well-ventilated place. Keep container tightly closed. Protect from sunlight. Do not expose to temperatures exceeding 50 °C/122° F. Keep container dry.
Spillage
Avoid entering drains, sewers or watercourses. Large Spillage: Contain and absorb. Small Spillage: Wipe away with paper or textile fabric – See SWP-19
Disposal of Substance & Contaminated Containers

☐ Hazardous Waste	☐ General Waste	✓ Return to Depot	☐ Return to Supplier	☐ Other

Additional Information:

Is exposure adequately controlled	Yes ✓	No ☐

Risk Rating Following Control Measures					
High ☐		Medium ☐		Low ✓	
Assessed by:	Elaine Greaves	Date:	Feb 2026	Review Date:	August 2027