TOYOTA

MATERIAL HANDLING

COSHH Risk Assessment:

Part Number: FMC002PRO

Name of Substance involved in the process *(a copy of the current safety data sheet is available)*	BARCOAT ISOLATOR (BAR)	Pseudonym	Barcoat Primer
Describe the activity or work process & exposure *(Inc. how long/how often this is carried out)*	Primer for MHE refurbishment Use: quarterly. approximately 4 hours a day, for 3 days	Location of process being carried out	TMHUK Paintshops

Identify the persons at risk	Team members	Sub-contractors	Customer Team member	Public
	[√]	[ ]	[ ]	[ ]

Labelling Elements


[ ] Explosive


[ ] Health Hazard


[ ] Serious Health Hazard


[ ] Oxidising


[ ] Corrosive


[ ] Acute


[√] Flammable


[ ] Environmental


[ ] Gas

Hazard Type

Gas	Vapour	Mist	Fume	Dust	Liquid	Solid	Other
[ ]	[√]	[ ]	[ ]	[ ]	[√]	[ ]	[ ]

Additional Information:

Route of Exposure & Possible Symptoms

Inhalation	Skin	Eyes	Ingestion	Other
[ ]	[ ]	[ ]	[ ]	[ ]

Additional Information:

Control Measures

See SWP-25.

Ensure good ventilation when using. Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. Use only non-sparking tools. Take precautionary measures against static discharge. Wear PPE as listed below.

Do not eat, drink or smoke when using this product. Always wash hands after handling the product.
This product poses no significant risk if used as intended in the amount anticipated, and manufactures instructions are followed.

Is health surveilance or monitoring required?	Yes	No
	[ ]	[√]

Provide details:

Personal Protective Equipment Required

COSHH Risk Assessment:

Part Number: FMC002PRO

							
Dust Mask	Visor	Respirator	Goggles	Gloves	Overalls	Footwear	Other
			√	√	√	√	

Additional Information: In case of insufficient ventilation, wear suitable respiratory equipment

First Aid Measures	
Inhalation:	Remove person to fresh air and keep comfortable for breathing.
Skin Contact:	Rinse skin with water/shower. Take off immediately all contaminated clothing.
Eye Contact:	Rinse eyes with water as a precaution.
Ingestion:	Call a poison center or a doctor if you feel unwell.

Storage
Store in a well-ventilated place. < 25 °C. Keep cool. Keep container tightly closed.
Spillage
See SWP-19. Wear Safety glasses. Protective clothing. Gloves. Ventilate spillage area. No open flames, no sparks, and no smoking. Avoid release to the environment. Take up liquid spill into absorbent material. Notify authorities if product enters sewers or public waters.
Disposal of Substance & Contaminated Containers

		√		
Hazardous Waste	General Waste	Return to Depot	Return to Supplier	Other

Additional Information:

Is exposure adequately controlled	Yes √	No
Risk Rating Following Control Measures		
High	Medium	Low √

Assessed by:	Elaine Greaves	Date:	November 2026	Review Date:	May 2028