TOYOTA

MATERIAL HANDLING

COSHH Risk Assessment:

Part Number: 263096-005UAD

Name of Substance involved in the process *(a copy of the current safety data sheet is available)*	TUNDRA 32	Pseudonym	Cold store oil
Describe the activity or work process & exposure *(Inc. how long/how often this is carried out)*	FLT Miantenance Use: Infrequent, less than weekly	Location of process being carried out	Customers Site, Toyota workshops

Identify the persons at risk	Team members √	Sub-contractors	Customer Team member √	Public

Labelling Elements


Explosive ☐


Health Hazard ☐


Serious Health Hazard ☐


Oxidising ☐


Corrosive ☐


Acute ☐


Flammable ☐


Environmental √


Gas ☐

Hazard Type

Gas	Vapour	Mist	Fume	Dust	Liquid	Solid	Other
☐	√	√	☐	☐	√	☐	☐

Additional Information: Oily Liquid

Route of Exposure & Possible Symptoms

Inhalation	Skin	Eyes	Ingestion	Other
☐	√	√	☐	☐

Additional Information: May produce an allergic reaction. May cause slight irritation.

Control Measures

For professional use only. Use in accordance with the instructions on the packaging. Keep stock levels to as minimum as possible. Ensure spill kits are available prior to use and clean up spills immediately. Wear appropriate PPE at all times as listed below and in SM-23.
Do not get in eyes, on skin, or on clothing.
No open flames. No smoking.
Wash hands and other exposed areas with mild soap and water before eating, drinking or smoking and when leaving work.
Do not eat, drink or smoke when using this product.
Separate working clothes from town clothes. Launder separately.
Eye protection should only be necessary where liquid could be splashed or sprayed.
Ensure good ventilation in process area to prevent formation of vapour. Avoid the formation of mists in the atmosphere. If this material is handled at elevated temperature or under mist forming conditions, approved respiratory protection equipment should be used. Wear appropriate mask

This product poses no significant risk if used as intended in the amount anticipated, and manufactures instructions are followed.

Authorisation: QSE Manager
Approval: QSE Team

COSHH Risk Assessment:

Part Number: 263096-005UAD

Is health surveilance or monitoring required?	Yes		No	√

Provide details:

Personal Protective Equipment Required

							
			√	√	√	√	
Dust Mask	Visor	Respirator	Goggles	Gloves	Overalls	Footwear	Other

Additional Information:

First Aid Measures	
Inhalation:	When symptoms occur: go into open air and ventilate suspected area. Assure fresh air breathing. Allow the victim to rest.
Skin Contact:	Rinse skin with water/shower. Wash contaminated clothing before reuse. Remove affected clothing and wash all exposed skin area with mild soap and water, followed by warm water rinse.
Eye Contact:	IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.
Ingestion:	Rinse mouth. Call a POISON CENTER/doctor if you feel unwell. Do NOT induce vomiting. Obtain emergency medical attention.

Storage

Store in original container. Keep container closed when not in use. Store in a dry, well ventilated place away from sources of heat, ignition and direct sunlight. Keep in fireproof place. Store away from heat. Floors should be impervious, resistant to liquids and easy to clean.

Spillage

May be dangerously slippery if spilled. Clean up any spills as soon as possible, using an absorbent material to collect it. Ventilate area. Collect all waste in suitable and labelled containers and dispose according to local legislation. See SWP-19.

Disposal of Substance & Contaminated Containers

√		√		
Hazardous Waste	General Waste	Depot	Return to Supplier	Other

Additional Information: Dispose of contents and container to a hazardous or special waste collection point.

Is exposure adequately controlled	Yes	√	No	

Risk Rating Following Control Measures

High		Medium		Low	√

Assessed by:	Elaine Greaves	Date:	Feb 2026	Review Date:	August 2027