TOYOTA

MATERIAL HANDLING

COSHH Risk Assessment:

Part Number: 388-3915RAG

Name of Substance involved in the process *(a copy of the current safety data sheet is available)*	Loctite 598	Pseudonym	Loctite 598
Describe the activity or work process & exposure *(Inc. how long/how often this is carried out)*	FLT Maintenance. Silicone Sealant. Less than weekly minutes at a time	Location of process being carried out	Customer Premises TMHUK Workshops

Identify the persons at risk	Team members √	Sub-contractors ☐	Customer Team member ☐	Public ☐

Labelling Elements


☐ Explosive


√ Health Hazard


√ Serious Health Hazard


☐ Oxidising


√ Corrosive


☐ Acute


☐ Flammable


☐ Environmental


☐ Gas

Signal Word: DANGER. May cause an allergic skin reaction. Causes serious eye damage. May cause cancer. May cause damage to organs.

Hazard Type

Gas	Vapour	Mist	Fume	Dust	Liquid	Solid	Other
☐	☐	☐	☐	☐	☐	☐	√

Additional Information: Paste. Copper in colour

Route of Exposure & Possible Symptoms

Inhalation	Skin	Eyes	Ingestion	Other
☐	√	√	☐	☐

Additional Information: SKIN: Rash, Urticaria.

After eye contact: Corrosive, may cause permanent damage to eyes (impairment of vision).

Control Measures

Wear protective gloves/protective clothing/eye protection/face protection.

Avoid skin and eye contact.

Good industrial hygiene practices should be observed. Wash hands before work breaks and after finishing work.

Do not eat, drink or smoke while working.

Ensure good ventilation/extraction when in use.

This product poses no significant risk if used as intended in the amount anticipated, and manufactures instructions are followed.

Is health surveilance or monitoring required?	Yes ☐	No √

Provide details:

Authorisation: QSE Manager

Approval: QSE Team

COSHH Risk Assessment:

Part Number: 388-3915RAG

Personal Protective Equipment Required							
			 √	 √	 √	 √	
Dust Mask	Visor	Respirator	Goggles	Gloves	Overalls	Footwear	Other
		EN14387	EN166	EN374	EN14605		

Additional Information: An approved mask or respirator fitted with an organic vapour cartridge should be worn if the product is used in a poorly ventilated area Filter type: A

First Aid Measures	
Inhalation:	Move to fresh air. If symptoms persist, seek medical advice.
Skin Contact:	Rinse with running water and soap. Obtain medical attention if irritation persists.
Eye Contact:	Rinse immediately with plenty of running water (for 10 minutes), seek medical attention from a specialist.
Ingestion:	Rinse mouth, drink 1-2 glasses of water, do not induce vomiting, consult a doctor.

Storage

Keep stock levels to a minimum. Ensure good ventilation/extraction. Store in a cool, well-ventilated place. Never allow product to get in contact with water during storage

Spillage

See SWP-19. Wear protective equipment. Ensure adequate ventilation. Do not empty into drains / surface water / ground water. Scrape up as much material as possible.
Sweep up spilled material. Avoid creating dust. Store in a partly filled, closed container until disposal.
Dispose of contaminated material as below.

Disposal of Substance & Contaminated Containers

Hazardous Waste	General Waste	Depot	Return to Supplier	Other
√				

Additional Information:

Is exposure adequately controlled	Yes √	No

Risk Rating Following Control Measures

High	Medium √	Low

Assessed by:	Elaine Greaves	Date:	April 2026	Review Date:	October 2027