TOYOTA

MATERIAL HANDLING

# COSHH Risk Assessment:

## Part Number: 641977-00PRO

| | | | |
|---|---|---|---|
| Name of Substance involved in the process *(a copy of the current safety data sheet is available)* | MOBIL SHC POLYREX 462 | Pseudonym | Bearing Grease |
| Describe the activity or work process & exposure *(Inc. how long/how often this is carried out)* | Truck radial bearing grease. Use: less than weekly lees than 10 minutes at a time | Location of process being carried out | Customer Premises & TMHUK Workshops |

| Identify the persons at risk | Team members | Sub-contractors | Customer Team member | Public |
|---|---|---|---|---|
| | ☐ | ☐ | √ | ☐ |

**Labelling Elements**


☐ Explosive


☐ Health Hazard


☐ Serious Health Hazard


☐ Oxidising


☐ Corrosive


☐ Acute


☐ Flammable


☐ Environmental


☐ Gas

No Pictograms, No Signal Word

**Hazard Type**

| Gas | Vapour | Mist | Fume | Dust | Liquid | Solid | Other |
|---|---|---|---|---|---|---|---|
| ☐ | ☐ | ☐ | ☐ | ☐ | ☐ | √ | ☐ |

Additional Information: Semi-fluid

**Route of Exposure & Possible Symptoms**

| Inhalation | Skin | Eyes | Ingestion | Other |
|---|---|---|---|---|
| ☐ | √ | ☐ | ☐ | ☐ |

Additional Information: High-pressure injection under skin may cause serious damage. Excessive exposure may result in eye, skin, or respiratory irritation.

**Control Measures**

Prevent small spills and leakage to avoid slip hazard.
There are no special levels of protection or controls required under ordinary conditions of use and with adequate ventilation.
Personal Protection requirements detailed below
In accordance with good industrial hygiene practices, precautions should be taken to avoid skin contact. Always observe good personal hygiene measures, such as washing after handling the material and before eating, drinking, and/or smoking. Routinely wash work clothing and protective equipment to remove contaminants. Discard contaminated clothing and footwear that cannot be cleaned. Practice good housekeeping.
Good general ventilation should be sufficient to control worker exposure to airborne contaminants.
Not expected to cause significant health effects under conditions of normal use
**This product poses no significant risk if used as intended in the amount anticipated, and manufactures instructions are followed.**

| Is health surveilance or monitoring required? | Yes | No |
|---|---|---|
| | ☐ | √ |

## COSHH Risk Assessment:

**Part Number: 641977-00PRO**

Provide details:

| Personal Protective Equipment Required | | | | | | | |
|---|---|---|---|---|---|---|---|
|  |  |  |  √ |  √ |  √ |  |  |
| Dust Mask | Visor | Respirator | Goggles | Gloves | Overalls | Footwear | Other |
| | | | | | | | |

Additional Information: If contact is likely, safety glasses with side shields are recommended.

| First Aid Measures | |
|---|---|
| **Inhalation:** | Under normal conditions of intended use, this material is not expected to be an inhalation hazard. Remove victim to fresh air and keep at rest in a position comfortable for breathing. |
| **Skin Contact:** | Wash contact areas with soap and water. If product is injected into or under the skin, or into any part of the body, regardless of the appearance of the wound or its size, the individual should be evaluated immediately by a physician as a surgical emergency. Even though initial symptoms from high pressure injection may be minimal or absent, early surgical treatment within the first few hours may significantly reduce the ultimate extent of injury. |
| **Eye Contact:** | Immediately flush eyes with plenty of water, occasionally lifting the upper and lower eyelids. Check for and remove any contact lenses. Get medical attention if irritation occurs.. |
| **Ingestion:** | Wash out mouth with water. If material has been swallowed and the exposed person is conscious, give small quantities of water to drink. Do not induce vomiting unless directed to do so by medical personnel. |

| Storage |
|---|
| Do not store in open or unlabelled containers. Keep away from incompatible materials. |
| **Spillage** |
| See SWP-19. Avoid contact with spilled material. Additional protective measures may be necessary, depending on the specific circumstances. Prevent entry into waterways, sewers, basements or confined areas. Stop leak if you can do so without risk. Scrape up spilled material with shovels into a suitable container for recycle or disposal. |
| **Disposal of Substance & Contaminated Containers** |

| | | | | |
|---|---|---|---|---|
| | | √ | | |
| Hazardous Waste | General Waste | Depot | Return to Supplier | Other |

Additional Information:

| Is exposure adequately controlled | Yes √ | No |
|---|---|---|
| **Risk Rating Following Control Measures** | | |

| High | | Medium | | Low | √ |
|---|---|---|---|---|---|
| Assessed by: | Elaine Greaves | Date: | March 2026 | Review Date: | September 2027 |