TOYOTA

MATERIAL HANDLING

COSHH Risk Assessment:

Part Number: 784-0032RAG

Name of Substance involved in the process *(a copy of the current safety data sheet is available)*	Galva Bright	Pseudonym	Galva Bright
Describe the activity or work process & exposure *(Inc. how long/how often this is carried out)*	Metal galvanising spray to protect stainless HPT's. Use – less than weekly for a maximum of 4 hours	Location of process being carried out	TMHUK Paint shop

Identify the persons at risk	Team members √	Sub-contractors ☐	Customer Team member ☐	Public ☐

Labelling Elements


☐ Explosive


☐ Health Hazard


☐ Serious Health Hazard


☐ Oxidising


☐ Corrosive


☐ Acute


√ Flammable


√ Environmental


☐ Gas

Extremely flammable aerosol. Pressurised container: May burst if heated

Signal words: Danger

Hazard Type

Gas	Vapour	Mist	Fume	Dust	Liquid	Solid	Other
☐	☐	√	√	☐	√	☐	☐

Additional Information:

Route of Exposure & Possible Symptoms

Inhalation	Skin	Eyes	Ingestion	Other
√	√	√	√	√

Additional Information: Irritant. May cause dizziness. After Inhalation- Shortness of breath.

Control Measures

Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking.
Do not spray on an open flame or other ignition source.
Do not pierce or burn, even after use.
Ensure there is sufficient ventilation of the area. Do not handle in a confined space.
Use within the paint shop area and follow SWP-25.
Wash hands and other exposed areas with mild soap and water before eating, drinking or smoking and when leaving work. Provide good ventilation in process area to prevent formation of vapour. Do not spray on an open flame or other ignition source.

This product poses no significant risk if used as intended in the amount anticipated, and manufactures instructions are followed.

Is health surveilance or monitoring required?	Yes	☐	No	√

Authorisation: QSE Manager
Approval: QSE Team

COSHH Risk Assessment:

Part Number: 784-0032RAG

Provide details:

Personal Protective Equipment Required

							
Dust Mask	Visor	Respirator	Goggles	Gloves	Overalls	Footwear	Other
				Nitrile rubber gloves.			

Additional Information: In case of inadequate ventilation wear respiratory protection. As per SWP-25

First Aid Measures

Inhalation:	Cough. Allow affected person to breathe fresh air. Allow the victim to rest.
Skin Contact:	Remove affected clothing and wash all exposed skin area with mild soap and water, followed by warm water rinse.
Eye Contact:	Direct contact with the eyes is likely to be irritating. Rinse immediately with plenty of water. Obtain medical attention if pain, blinking or redness persists.
Ingestion:	Rinse mouth. Do NOT induce vomiting. Obtain emergency medical attention.

Storage

Protect from sunlight. Do not expose to temperatures exceeding 50 ºC.
Proper grounding procedures to avoid static electricity should be followed.
Store in a cool, well ventilated area. Keep away from sources of ignition. Keep away from direct sunlight.
Ensure lighting and electrical equipment are not a source of ignition.
Must only be kept in original packaging. Keep in fireproof place.

Spillage

Avoid release to the environment. Collect spillage. See SWP-19. Do not discharge into drains or rivers.
Do not use equipment in clean-up procedure which may produce sparks. Absorb into dry earth or sand.
Transfer to a closable, labelled salvage container for disposal by an appropriate method.

Disposal of Substance & Contaminated Containers

√				
Hazardous Waste	General Waste	Depot	Return to Supplier	Other

Additional Information:

Is exposure adequately controlled	Yes √	No

Risk Rating Following Control Measures

High	Medium	Low √

Assessed by:	Elaine Greaves	Date:	December 2024	Review Date:	June 2026