TOYOTA

MATERIAL HANDLING

COSHH Risk Assessment:

Part Number: D001S564CED

Name of Substance involved in the process *(a copy of the current safety data sheet is available)*	Opticool Antifreeze Blue	Pseudonym	Antifreeze
Describe the activity or work process & exposure *(Inc. how long/how often this is carried out)*	FLT Maintenance - Anti-Freeze and de-icing product. Use: frequent, possibly daily, a couple of minutes at a time.	Location of process being carried out	Customer's Site & Toyota Workshops

Identify the persons at risk	Team members √	Sub-contractors ☐	Customer Team member ☐	Public ☐

Labelling Elements

 ☐ Explosive

 √ Health Hazard

 √ Serious Health Hazard

 ☐ Oxidising

 ☐ Corrosive

 ☐ Acute

 ☐ Flammable

 ☐ Environmental

 ☐ Gas

Signal words: Warning

Hazard Type

Gas	Vapour	Mist	Fume	Dust	Liquid	Solid	Other
☐	☐	☐	☐	☐	√	☐	☐

Additional Information: Blue Liquid

Route of Exposure & Possible Symptoms

Inhalation	Skin	Eyes	Ingestion	Other
☐	√	☐	√	☐

Additional Information: Irritant. Harmful if swallowed. May cause damage to organs through prolonged or repeated exposure ([oral]).

Control Measures

Avoid the formation or spread of mists in the air. Avoid direct contact with the substance.
Ensure eye bath is to hand when using

Wear appropriate PPE. Good general ventilation required. Avoid inhalation of vapours/spray and contact with skin and eyes. Do not ingest.
Stock levels to be kept to a minimum where practicable.

Good personal hygiene is necessary. Wash hands at the end of each work shift and before eating, drinking, smoking and using the toilet.
Do not eat, drink or smoke when using the product.

This product poses no significant risk if used as intended in the amount anticipated, and manufactures instructions are followed.

COSHH Risk Assessment:

Part Number: D001S564CED

Is health surveilance or monitoring required?	Yes ☐	No √

Provide details:

Personal Protective Equipment Required

							
Dust Mask ☐	Visor ☐	Respirator ☐	Goggles √	Gloves √	Overalls √	Footwear √	Other ☐

Additional Information:

First Aid Measures	
Inhalation:	Remove person to fresh air and keep comfortable for breathing.
Skin Contact:	Wash skin with plenty of water.
Eye Contact:	Bathe the eye with running water for 15 minutes.
Ingestion:	Wash out mouth with water. Do not induce vomiting. If conscious, give half a litre of water to drink immediately. Transfer to hospital as soon as possible.

Storage

Store in a cool, well ventilated area. Keep container tightly closed. Materials to avoid: Strong oxidising agents. Strong acids.

Spillage

See SWP-19. Ventilate spillage area. Do not breathe dust/fume/gas/mist/vapours/spray. Mark out the contaminated area with signs and prevent access to unauthorised personnel. Turn leaking containers leak-side up to prevent the escape of liquid. Do not discharge into drains or rivers. Contain the spillage using bunding. Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by an appropriate method.

Disposal of Substance & Contaminated Containers

Hazardous Waste ☐	General Waste ☐	Depot √	Return to Supplier ☐	Other ☐

Additional Information:

Is exposure adequately controlled	Yes √	No ☐

Risk Rating Following Control Measures

High ☐ Medium ☐ Low √

Assessed by:	Elaine Greaves	Date:	June 2024	Review Date:	December 2025