TOYOTA

MATERIAL HANDLING

# COSHH Risk Assessment:

## Part Number: GB1PAL001538

| | | | |
|---|---|---|---|
| Name of Substance involved in the process *(a copy of the current safety data sheet is available)* | AdBlue urea solution | Pseudonym | AdBlue |
| Describe the activity or work process & exposure *(Inc. how long/how often this is carried out)* | Vehicle Maintenance. Use: less than monthly for minutes at a time. | Location of process being carried out | TMHUK Depots and Users property. |

| | | | | |
|---|---|---|---|---|
| Identify the persons at risk | Team members √ | Sub-contractors ☐ | Customer Team member ☐ | Public ☐ |

**Labelling Elements**

 ☐ Explosive

 ☐ Health Hazard

 ☐ Serious Health Hazard

 ☐ Oxidising

 ☐ Corrosive

 ☐ Acute

 ☐ Flammable

 ☐ Environmental

 ☐ Gas

Not Classified

**Hazard Type**

| Gas | Vapour | Mist | Fume | Dust | Liquid | Solid | Other |
|---|---|---|---|---|---|---|---|
| ☐ | ☐ | ☐ | ☐ | ☐ | √ | ☐ | ☐ |

Additional Information:

**Route of Exposure & Possible Symptoms**

| Inhalation | Skin | Eyes | Ingestion | Other |
|---|---|---|---|---|
| ☐ | ☐ | √ | ☐ | ☐ |

Additional Information: Slight irritation.

**Control Measures**

Wear PPE as listed below.

Keep good industrial hygiene. Wash hands and other exposed areas with mild soap and water before eating, drinking or smoking and when leaving work. Do not eat, drink or smoke when using this product. Keep away from food, drink and animal feedingstuffs. Remove contaminated clothes. Separate working clothes from town clothes. Launder separately. Wash contaminated clothing before reuse.

Keep away from open flames, hot surfaces and sources of ignition. Keep out of direct sunlight. Do not smoke.

**This product poses no significant risk if used as intended in the amount anticipated, and manufactures instructions are followed.**

| Is health surveilance or monitoring required? | Yes ☐ | No √ |
|---|---|---|

Provide details:

## COSHH Risk Assessment:

**Part Number: GB1PAL001538**

| Personal Protective Equipment Required | | | | | | | |
|---|---|---|---|---|---|---|---|
|  |  |  |  √ |  √ |  √ |  √ |  |
| Dust Mask | Visor | Respirator | Goggles | Gloves | Overalls | Footwear | Other |
| | | | EN166 | chemically resistant gloves | | | |

Additional Information:

| First Aid Measures | |
|---|---|
| **Inhalation:** | Remove person to fresh air and keep comfortable for breathing. In case of doubt or persistent symptoms, consult always a physician. |
| **Skin Contact:** | Take off contaminated clothing. Gently wash with plenty of soap and water. In case of doubt or persistent symptoms, consult always a physician. |
| **Eye Contact:** | Rinse immediately with plenty of water for at least 15 minutes. In case of doubt or persistent symptoms, consult always a physician. |
| **Ingestion:** | Rinse mouth immediately and drink plenty of water. In case of doubt or persistent symptoms, consult always a physician. |

| Storage |
|---|
| Store in a dry, cool and well-ventilated place. Do not store near or with any of the incompatible materials. Bund storage facilities to prevent soil and water pollution in the event of spillage. Keep only in the original container. Storage temperature: >-10 - <=25 °C |
| **Spillage** |
| See SWP-19. Do not allow to enter into surface water or drains. Notify authorities if product enters sewers or public waters. Stop leak if safe to do so. Dam up the liquid spill. take up in non-combustible absorbent material and shovel into container for disposal. |
| **Disposal of Substance & Contaminated Containers** |

| | | | | |
|---|---|---|---|---|
| | | √ | | |
| Hazardous Waste | General Waste | Depot | Return to Supplier | Other |

Additional Information:

| | | | | | |
|---|---|---|---|---|---|
| Is exposure adequately controlled | Yes √ | No | | | |
| Risk Rating Following Control Measures | | | | | |
| High | | Medium | | Low √ | |
| Assessed by: | Elaine Greaves | Date: | June 2024 | Review Date: | December 2025 |