TOYOTA

MATERIAL HANDLING

COSHH Risk Assessment:

Part Number: R251CED

Name of Substance involved in the process *(a copy of the current safety data sheet is available)*	Graffiti Remover	Pseudonym	Graffiti Remover
Describe the activity or work process & exposure *(Inc. how long/how often this is carried out)*	FLT Maintenance Use: Rarely, less than weekly, for short periods, a few minutes at a time whilst cleaning panels.	Location of process being carried out	Customers Site Toyota Workshops

Identify the persons at risk	Team members ✓	Sub-contractors ☐	Customer Team member ☐	Public ☐

Labelling Elements


☐ Explosive


✓ Health Hazard


☐ Serious Health Hazard


☐ Oxidising


✓ Corrosive


☐ Acute


✓ Flammable


☐ Environmental


☐ Gas

Signal Word: DANGER

Hazard Type

Gas	Vapour	Mist	Fume	Dust	Liquid	Solid	Other
☐	✓	✓	☐	☐	✓	☐	☐

Additional Information: Aerosol

Route of Exposure & Possible Symptoms

Inhalation	Skin	Eyes	Ingestion	Other
✓	✓	✓	✓	☐

Additional Information: Irritant

Control Measures

Extremely flammable aerosol. May cause drowsiness or dizziness.
Keep out of reach of children. Keep away from heat/sparks/open flames/hot surfaces. - No smoking.
Use only outdoors or in a well-ventilated area.
Wear PPE according to SWP-32.
Avoid spilling, skin and eye contact.
Ventilate well, avoid breathing vapours. Use approved respirator if air contamination is above accepted level.
Avoid release to the environment.
DO NOT SMOKE IN WORK AREA! Wash hands at the end of each work shift and before eating, smoking and using the toilet. Promptly remove any clothing that becomes contaminated. When using do not eat, drink or smoke.
This product poses no significant risk if used as intended in the amount anticipated, and manufactures instructions are followed.

COSHH Risk Assessment:

Part Number: R251CED

Is health surveilance or monitoring required?	Yes ☐	No ☑

Provide details:

Personal Protective Equipment Required

 ☐ Dust Mask
 ☐ Visor
 ☐ Respirator
 ☑ Goggles
 ☑ Gloves
 ☑ Overalls
 ☑ Footwear
 ☐ Other

Additional Information:

First Aid Measures

Inhalation:	Move the exposed person to fresh air at once. When breathing is difficult, properly trained personnel may assist affected person by administering oxygen. Keep the affected person warm and at rest. Get prompt medical attention.
Skin Contact:	Wash the skin immediately with soap and water. Get medical attention if any discomfort continues.
Eye Contact:	Make sure to remove any contact lenses from the eyes before rinsing. Promptly wash eyes with plenty of water while lifting the eye lids. Continue to rinse for at least 15 minutes. Get medical attention if any discomfort continues.
Ingestion:	DO NOT INDUCE VOMITING! Rinse mouth thoroughly with water and give large amounts of milk or water to people not unconscious. Get medical attention if any discomfort continues.

Storage

Aerosol cans: Must not be exposed to direct sunlight or temperatures above 50°C. Keep in a cool, well ventilated place away from heat. Store locked up. Keep container tightly closed.

Spillage

Wear necessary protective equipment. Extinguish all ignition sources. Avoid sparks, flames, heat and smoking. Ventilate. Let evaporate. Keep out of confined spaces because of explosion risk. If leakage cannot be stopped, evacuate area.

Disposal of Substance & Contaminated Containers

☐ Hazardous Waste ☐ General Waste ☑ Return to Depot ☐ Return to Supplier ☐ Other

Additional Information: Do not pierce or burn even after use

Is exposure adequately controlled	Yes ☑	No ☐

Risk Rating Following Control Measures

High ☐ Medium ☐ Low ☑

Assessed by:	Elaine Greaves	Date:	Feb 2026	Review Date:	August 2027