TOYOTA

MATERIAL HANDLING

COSHH Risk Assessment:

Part Number: SOL7329300K-CRC

Name of Substance involved in the process *(a copy of the current safety data sheet is available)*	WELDERS ANTI-SPATTER FLUID - 5L	Pseudonym	Anti-Spatter
Describe the activity or work process & exposure *(Inc. how long/how often this is carried out)*	FLT repairs, Welding work. Reduces spatter. Use: less than daily, minutes at a time.	Location of process being carried out	TMHUK Workshop – Welding Bay

Identify the persons at risk	Team members √	Sub-contractors ☐	Customer Team member ☐	Public ☐

Labelling Elements

 ☐ Explosive

 √ Health Hazard

 ☐ Serious Health Hazard

 ☐ Oxidising

 ☐ Corrosive

 ☐ Acute

 ☐ Flammable

 ☐ Environmental

 ☐ Gas

Signal Word: WARNING

Hazard Type

☐ Gas	√ Vapour	☐ Mist	☐ Fume	☐ Dust	√ Liquid	☐ Solid	☐ Other

Additional Information:

Route of Exposure & Possible Symptoms

☐ Inhalation	☐ Skin	√ Eyes	☐ Ingestion	☐ Other

Additional Information: Causes serious eye irritation.

Control Measures

Ensure good ventilation of the work station. Avoid contact with skin and eyes. Wear personal protective equipment: protective gloves/protective clothing/eye protection/face protection/hearing protection.
Do not eat, drink or smoke when using this product. Always wash hands after handling the product.
This product poses no significant risk if used as intended in the amount anticipated, and manufactures instructions are followed.

Is health surveilance or monitoring required?	Yes ☐	No √

Provide details:

Personal Protective Equipment Required

☐ Dust Mask	☐ Visor	☐ Respirator	√ Goggles	√ Gloves	√ Overalls	☐ Footwear	☐ Other
			EN166	Wear Butyl rubber			

Authorisation: QSE Manager
Approval: QSE Team

				gloves			

Additional Information:

First Aid Measures	
Inhalation:	No Significant Hazard.
Skin Contact:	Wash skin with plenty of water.
Eye Contact:	Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists: Get medical advice/attention.
Ingestion:	Call a poison center or a doctor if you feel unwell.

Storage
Store in a well-ventilated place. Keep cool. Keep stock levels to a minimum. Avoid release to the environment.
Spillage
See SWP-19. Take up liquid spill into absorbent material. Dispose of materials or solid residues at an authorized site. Avoid release to the environment. Ventilate spillage area. Avoid contact with skin and eyes.
Disposal of Substance & Contaminated Containers

☐	☑	☐	☐	☐
Hazardous Waste	General Waste	Depot	Return to Supplier	Other

Additional Information:

Is exposure adequately controlled	Yes ☐	No ☐
Risk Rating Following Control Measures		
High ☐	Medium ☐	Low ☑

Assessed by:	Elaine Greaves	Date:	November 2024	Review Date:	May 2026