TOYOTA

MATERIAL HANDLING

COSHH Risk Assessment:

Part Number: WA0001

Name of Substance involved in the process *(a copy of the current safety data sheet is available)*	Penetrative Primer	Pseudonym	Penetrative Primer
Describe the activity or work process & exposure *(Inc. how long/how often this is carried out)*	FLT – Preparation – Vehicle Underbody Coating.	Location of process being carried out	Warrington Spray Booth

Identify the persons at risk	Team members √	Sub-contractors √	Customer Team member ☐	Public ☐

Labelling Elements

 ☐ Explosive

 √ Health Hazard

 ☐ Serious Health Hazard

 ☐ Oxidising

 ☐ Corrosive

 ☐ Acute

 √ Flammable

 ☐ Environmental

 ☐ Gas

Signal Word: Warning

Hazard Type

Gas	Vapour	Mist	Fume	Dust	Liquid	Solid	Other
☐	√	√	☐	☐	√	☐	☐

Additional Information:

Route of Exposure & Possible Symptoms

Inhalation	Skin	Eyes	Ingestion	Other
√	√	√	√	☐

Additional Information: Irritant

Control Measures

Only to be used in spray booth – SWP-25 followed.
Flammable liquid and vapour. May cause drowsiness or dizziness.
IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water.
Avoid direct contact with the substance.
Ensure there is sufficient ventilation of the area.
Do not handle in a confined space.
Avoid the formation or spread of mists in the air.
Smoking is forbidden. Use non-sparking tools.

Wear PPE as listed below.

This product poses no significant risk if used as intended in the amount anticipated, and manufactures instructions are followed.

Is health surveilance or monitoring required?	Yes ☐	No √

Provide details:

COSHH Risk Assessment:

Part Number: WA0001

Personal Protective Equipment Required							
			 √	 √	 √	 √	
Dust Mask	Visor	Respirator	Goggles	Gloves	Overalls	Footwear	Other

Additional Information:

First Aid Measures	
Inhalation:	Remove casualty from exposure ensuring one's own safety whilst doing so. Consult a doctor.
Skin Contact:	Remove all contaminated clothes and footwear immediately unless stuck to skin. Wash immediately with plenty of soap and water.
Eye Contact:	Bathe the eye with running water for 15 minutes. Consult a doctor.
Ingestion:	Wash out mouth with water. Consult a doctor.

Storage
Keep out of reach of children. Protect from freezing and direct sunlight. Store in a dry place. Do not store near heat sources or expose to high temperatures. Keep away from heat, sparks and open flame. Store in a cool, well ventilated area. Keep container tightly closed. Keep away from sources of ignition. Prevent the build up of electrostatic charge in the immediate area. Ensure lighting and electrical equipment are not a source of ignition. Must only be kept in original packaging.
Spillage
See SWP-19. Turn leaking containers leak-side up to prevent the escape of liquid. Eliminate all sources of ignition. Do not discharge into drains or rivers. Contain the spillage using bunding. Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for disposal by an appropriate method. Do not use equipment in clean-up procedure which may produce sparks.
Disposal of Substance & Contaminated Containers

		√		
Hazardous Waste	General Waste	Depot	Return to Supplier	Other

Additional Information:

Is exposure adequately controlled	Yes √	No
Risk Rating Following Control Measures		

High		Medium		Low	√

Assessed by:	Elaine Greaves	Date:	May 2023	Review Date:	May 2028